

35 East Chestnut

Installation

2006

Location

Columbus, OH

Materials

Strongcote SC-113 Vehicular Traffic Coating

Strongcrete SW-81 Repair Mortar

Contractor

Lithko Restoration

After extensive full depth repairs on this 104,000 sq.ft. Columbus, OH garage, the contractor chose to coat the surface with Strongwall's SC-113 vehicular traffic coating. The contractor wanted a coating that was durable and had superior traction. Zero Voc's in the occupied building was also important.

